

Oil Field Environmental Incident Summary

Incident: 20150507113747 **Date/Time of Notice:** 05/07/2015 11:37

Responsible Party: Petro-Hunt,LLC

Well Operator: PETRO-HUNT, L.L.C.

Well Name: Killdeer Mountain Pipeline

Field Name: LITTLE KNIFE

Well File #:

Date Incident: 5/6/2015 **Time Incident:** 10:30

Facility ID Number:

County: DUNN

Twp: 147

Rng: 97

Sec: 22

Qtr: SE

Location Description: Release is on pipeline ROW in SE Qtr of Section 22 T147N R97 W.

Submitted By: Rodney Krogh

Received By:

Contact Person: Rodney Krogh
813 123rd Ave SW
Killdeer, ND 58640

General Land Use: Pasture

Affected Medium: Topsoil

Distance Nearest Occupied Building: 1 Mile

Distance Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained in Dike: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	300	Gallons				

Description of Other Released Contaminant:

Unprocessed natural gas in mcf

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Explosive atmosphere at leak until pipeline is depressured

Areal Extent:

Potential Environmental Impacts:

Not likely to have environmental impact

Action Taken or Planned:

Pipeline is shut in and depressured. Line will be repaired and will look for less vulnerable ROW.

Wastes Disposal Location: NA

Agencies Involved:

Updates

Date: 5/7/2015 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary, this spill occurred along a pipeline right of way. Followup is necessary.

Date: 5/22/2015 **Status:** Correspondence

Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

I called the company contact on the spill report to get better directions to the break site. The best way to get to the site is from the north following the west side of Section 14. Contact indicated that the break occurred on a hillside that has slid down, causing pressure on the line. The line has been repaired, and he also indicated that NDIC Oil and Gas personnel had looked at the site.

Date: 5/26/2015 **Status:** Inspection

Author: Crowdus, Kory

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

At location 5/26/15, at 11:40 a.m. Was in the area of release as noted on report. I could not see any remaining impact from release. No further followup required at this time.